

MAINTENANCE HISTORY

Generation date: 2026/07/06

Plate Number **S7-89-KP**
 Make **RENAULT**
 Model **CLIO**
 Vehicle Description **1.0 TCe 90 GPF Equilibre 5d**

DATE	MILEAGE	TYPE	DESCRIPTION	SUPPLIER
2024/09/11	0 KM	damage	Deur RV Inname Flex Fleet	Schadenet Janson, Autoschadebedrijf B.V.,
2024/09/10	0 KM	damage	Rechts achter Inname Flex Fleet	Schadenet Janson, Autoschadebedrijf B.V.,
2024/09/09	0 KM	damage	Links achter Inname Flex Fleet	Schadenet Janson, Autoschadebedrijf B.V.,
2024/09/08	0 KM	damage	Achterklep/kofferd. Interieur Inname Flex Fleet	Schadenet Janson, Autoschadebedrijf B.V.,
2024/06/05	0 KM	damage	Wiel LV Wioldop Inname Flex Fleet	Bosch Car Service Jaspers, ,
2023/07/21	0 KM	damage	Links achter Achterbumper (onb) tpy, geen WBF	Joustra Merkenherstel, ,
2025/09/15	43480 KM	repair	- Bandvervanging - NVT - Uitvoeren Int luchtfilter - versleten - Vervangen Renault OH B - NVT - Uitvoeren	- Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, ,

			Ruitenw.blad A - versleten - Vervangen	• Bosch Car Service Park Honingen, , • Bosch Car Service Park Honingen, ,
2024/03/06	17629 KM	repair	• Renault OH A - NVT - Uitvoeren	• James Auto Service Weijers, ,
2023/08/03	1 KM	repair	• Banden - NVT - Uitvoeren	• Lease Plan Nederland N.V., ,
2023/08/01	10 KM	repair	• Bandvervanging - NVT - Uitvoeren	• Renault dealer Bochane Zeist, ,